HISTORIC AMERICAN ENGINEERING RECORD

HAER UTAH 7-DUCH.V, 1K_

Index to Photographs

Irrigation Canals in the Uinta Basin,
Rocky Point Canai
Duchesne Vicinity
Duchesne County
Utah

HAER No. UT-30-K

NOTE: Photographs were taken by Clayton B. Fraser, Fraserdesign, August 1983

UT-30-K-1	OVERALL VIEW OF CANAL AND DUCHESNE RIVER VALLEY, LOOKING SOUTHEAST
UT-30-K-2	OVERALL VIEW OF CANAL AND DUCHESNE RIVER VALLEY, LOOKING NORTHEAST
UT-30-K-3	VIEW OF CANAL, LOOKING NORTH
UT-30-K-4	VIEW OF CANAL WITH GAUGING STATION IN BACKGROUND, LOOKING NORTH
UT-30-K-5	VIEW OF SCREW-TYPE LATERAL GATE AND GAUGING STATION, LOOKING NORTH
UT-30-K-6	VIEW OF SCREW-TYPE LATERAL GATE, LOOKING SOUTHWEST
UT-30-K-7	VIEW OF CANAL, LOOKING SOUTH
UT-30-K-8	VIEW OF CONCRETE CHUTE AT GAUGING STATION, LOOKING SOUTHWEST
UT-30-K-9	VIEW OF WOOD HEADGATE, LOOKING SOUTH
UT-30-K-10	VIEW OF WOOD HEADGATE, LOOKING SOUTHWEST
UT-30-K-11	VIEW OF WOOD HEADGATE, LOOKING SOUTHEAST
UT-30-K-12	VIEW OF WOOD HEADGATE, LOOKING SOUTHEAST
UT-30-K-13	VIEW OF WOOD HEADGATE, LOOKING EAST

Note: For a list of all documented structures in the Uinta Basin, see HAER UT-30.